## IL 50 @ ARMOUR RD




#1: Looking west toward Locke Drive (e/o IL50)



#2: Looking west toward IL50 from east leg Armour Rd



#3: Looking west along Armour Rd across IL50



#4: Looking SW at roadside ditch and culverts in NE quadrant

## IL 50 @ ARMOUR RD



#5: Looking SE at roadside ditch and culverts in NE quadrant



#6: Looking north at roadside ditch and culvert in SE quadrant



#7: Looking west at roadside ditch and culverts in NE quadrant



#8: Looking south along ditch in SE quadrant



#9: Looking north along IL50 toward Armour Rd



#10: Looking east at roadside ditch and culverts in SW quadrant



#11: Looking south along IL50 away from Armour Rd



#12: Looking east along Armour Rd toward IL50

Field Investigation Photo Log

## IL 50 @ ARMOUR RD



#13: Looking west along Armour Rd away from IL50 (at Birch Dr)



#14: Looking north along IL50 away from Armour Rd (at I-57)



#15: Looking SW at roadside ditch and culverts in NW quadrant



#16: Looking south along IL50 toward Armour Rd

Field Investigation Photo Log